

Facility Inspection Tool Summary of Ratings For Williams Facility Inspection

| school district/county office of education Los Angeles Unified (LAUSD) |) / Los Angeles County Office | | Los Angeles | | | | |
|------------------------------------------------------------------------|-------------------------------|----------------------|---------------------------------|----------------------------------|--|--|--|
| school site / ADDRESS Learning by Design Charter, | 7019 South Van Ness Ave., L | os Angeles, CA 90047 | SCHOOL TYPE (GRADE LEVELS) | NUMBER OF CLASSROOMS ON SITE 7 | | | |
| INSPECTOR'S NAME | | | NAME OF DISTRICT REPRESENTATIVE | TITLE OF DISTRICT REPRESENTATIVE | | | |
| Vallo, Anthony | | | Mrs. Harris | Principal/AP | | | |
| DATE OF INSPECTION 10/29/2024 am | FOLLOW-UP INSPECTION DATE: | Unannounced Visit | 19647330137513 | | | | |

| Total # of Category | A. SYSTEMS | | B. INTERIOR | C. CLEANLINESS | | D. ELECTRICAL | E. RESTROOMS/ FOUNTAINS | | F. SAFETY | | G. STRUCTURAL | | H. EXTERNAL | | | |
|--------------------------------------------------|----------------------------------------------|--------|-------------|----------------|----------------------|------------------------|----------------------------|------------|-----------|----------------------|---------------|-----------------------|-------------|--------------------|---------------------------------|------------------------------|
| Areas Evaluated | Totals | GAS | MECH/HVAC | SEWER | INTERIOR SURFACES | OVERALL CLEANLINESS | PEST/VERMIN INFESTATION | ELECTRICAL | RESTROOMS | SINKS / FOUNTAINS | FIRE SAFETY | HAZARDOUS MATERIAL | STRUCTURAL | ROOFS / GUTTERS | PLAYGROUND SCHOOL GROUNDS | Windows/Door Gates/Fences |
| | # of '√ "s | 12 | 12 | 12 | 5 | 12 | 13 | 11 | 5 | 12 | 11 | 12 | 12 | 12 | 13 | 13 |
| | # of "D"s | | | | 7 | 1 | | 1 | | | 1 | | | | | |
| 13 | # of "X"s | | | | | | | | | | | | | | | |
| 13 | # of "NA"s | 1 | 1 | 1 | 1 | | | 1 | 8 | 1 | 1 | 1 | 1 | 1 | | |
| # of √ 's | in Good Repair divided by as - "NA"s)* | 100.00 | 100.00 | 100.00 | 41.67 | 92.31 | 100.00 | 91.67 | 100.00 | 100.00 | 91.67 | 100.00 | 100.00 | 100.00 | 100.00 | 100.00 |
| • | er Category of above)* | | 100 | | 41.67 | 96. | 15 | 91.67 | 10 | 00 | 95 | .83 | 10 | 00 | 10 | 00 |
| Good=90-100% Rank Fair=75-89.99% Poor=0-74.99% | | | Good | | Poor | Good | | Good | Good | | Good | | Good | | Good | |

*Note - An extreme deficiency in any area automatically results in a "Poor" rating for that category and a zero for "Total % per Category".

| OVERALL RATING: | DETERMINE AVERAGE PERCENTAGE | OF 8 CATE | GORIES ABO | /E> | 90.67% | SCHOOL RATING -> | GOOD |) |
|-----------------|------------------------------|-----------|------------|----------|--------|-------------------------|----------|--------|
| Ratings | | | Site | Building | | | Students | Adults |
| Reduction | | SqFt | 48003 | 19.035 | | Female Fixtures | 12 | 0 |
| Rationale | | | | | | Male Urinals | 5 | 0 |
| | | | | | | Male Toilets | 5 | 0 |
| | | | | | | Gender-Neutral Fixtures | 0 | 3 |

| Percentage | Description | | | |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--|--|
| 99%-100% | The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of school. | Exemplary | | |
| 90%-98.99% | The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated. | Good | | |
| 75-89.99% | The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs an/or additional maintenance are necessary in several areas of the school site. | Fair | | |
| 0-74.99% | The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus. | Poor | | |

The Los Angeles County Office of Education provides observations on approximately 25-60% of classrooms, chosen at random, for this report. Not all deficiencies will be observed; this inspection is merely a snapshot in time showing the condition of the school on one day and is not meant to be comprehensive. It is the responsibility of the School and District to ensure that the site is kept in Good Repair as defined by Williams Legislation.

Page 1

As of 10/31/2024 at 2:34 PM

Detail Report Williams Facility Inspections School year 2024-2025



64733 - Los Angeles Unified (LAUSD)

19647330137513 - Learning by Design Charter

of Instruction Rooms 7 # Inspected 7 % Instruction Rooms 100%

Interior Surfaces

Classroom 2nd

Carpeting damaged or stained.

Classroom 3rd

Carpeting damaged or stained.

Classroom 4th/5th

Carpeting damaged or stained.

Classroom 5th

Carpeting damaged or stained.

Classroom intervention

Carpeting damaged or stained.

Classroom K1

Carpeting damaged or stained.

Classroom Tk

Carpeting damaged or stained.

Fire Safety

Classroom 5th

Exit door is blocked.

Electrical

Classroom K1

Improper usage of extension cords or extension cord trip hazard.

Improper usage of surge protectors or daisy chain of surge protectors.

Overall Cleanliness

Classroom intervention

Unsecured items stored too high

Detail Report Williams Facility Inspections School year 2024-2025



64733 - Los Angeles Unified (LAUSD)

19647330137513 - Learning by Design Charter

The following rooms were inspected:

1 - Girls RR Main - (no deficiencies) 6 - Classroom intervention

2 - Classroom K1 7 - Classroom 3rd 3 - Classroom Tk 8 - Classroom 5th

4 - Classroom 2nd 9 - Classroom 4th/5th

5 - Girls RR Up - (no deficiencies) 10 - Boys RR up - (no deficiencies)

11 - Boys RR Main - (no deficiencies)

12 - Kitchen/Cafe - (no deficiencies)

13 - Grounds - (no deficiencies)

OBSERVATIONS: None

District did not provide any comments about how they are addressing deficiencies.

Inspection Reviewed by:

Mrs. Harris Principal

10/29/2024 12:15:20 PM

Note: When a deficiency is observed that involves moisture of any kind, including, but not limited to a stained ceiling tile or damp carpeting, it is the responsibility of the District to perform any necessary testing to determine the source of the moisture or any other hazards and then provide appropriate repairs. This report is a list of observations only and is not intended to diagnose the cause of a deficiency.